# Sign finishing special pantone colours

(import this file into your design software to use the colours)

CutContour (used for shaped cuts)

DIE-CUT FORME (used for scores)

CutContour (used for Drill holes)

12mm standoffs   **6mm holes**   **3mm screw holes**

Spot1 (used for white ink layers)

Import the spot colour or set up a new one.

Make sure the spelling and case match ours.

Set the colour to preserve overprint.

Do not convert to CMYK.

Place the cut, drill hole or Spot white on the top layer of your design.

PDF Settings   ×

General | Color | Document | Objects | Prepress | Security | ☑ No Issues

┌─ Color management ────────────────────────────
  ⦿ Use document color settings
  ○ Use color proof settings
  Output colors as: [CMYK   ▼]
  ☐ Convert spot colors to: CMYK
  ☐ Embed color profile: ISO Coated v2 (ECI) - 1.74 MB

┌─ Other color controls ────────────────────────
  ☑ Preserve document overprints
  ☐ Always overprint black

                        [OK] [Cancel] [Help]